



**ROTARY CASEMENT OPERATORS EVALUATION  
AS PER AAMA 901 STANDARD**

PRODUCT MANUFACTURER
<b>FERCO ARCHITECTURAL HARDWARE INC.</b> 2000, rue Berlier Laval, Québec H7L 4S4 450-973-1437

REPORT AS-01452
-----------------

TEST REPORT SUMMARY	
<b>Product type</b>	Dual Arm Operator
<b>Evaluated product</b>	6-C2331-00-R-8
<b>Test results:</b>	The four Dual arm operators, as described in section 3 of this report, completed successfully the cycling of 8 000 cycles for the following window designation rating: C-AW40 and Class AW-PG40-C


See UL Laboratory Canada Inc. complete report AS-01452-A for test specimen description and detailed test results

<b>Test completion date</b>	2020-10-30	<b>Number of pages</b>	1 page
<b>Report date</b>	2021-02-02	<b>Revision date</b>	N/A

Prepared by:

  
**Justin Chagnon-Lafrance, Jr. Eng.**  
Project Manager, Materials and Systems Testing  
UL Laboratory Canada Inc.

Approved by:

  
**Jean Loubert, P.Eng.**  
Assistant manager, Materials and Systems Testing  
UL Laboratory Canada Inc.

LABORATORY, FIELD TESTING AND ADVISORY SERVICES FOR THE BUILDING ENVELOPE  
125 YEARS STRONG, UL LABORATORY CANADA INC. SERVING CUSTOMERS ACROSS NORTH AMERICA AND BEYOND

**CHICAGO**  
US Headquarters  
750 Anthony Trail  
Northbrook, IL 60062

**MONTREAL**  
Canada Headquarters  
1320 Lionel-Boulet Blvd  
Varenes, QC J3X 1P7

**TORONTO**  
7, Underwriters Road  
Toronto, ON  
M1R 3A9